



CCS-CFW11



Clamp
Abrazadera
Abraçadeira



* Screw M3 x 8
Tornillo M3 x 8
Parafuso M3 x 8



* Screw M4 x 10
Tornillo M4 x 10
Parafuso M4 x 10



* Spacer M3 x 5.8
Separador M3 x 5.8
Espaçador M3 x 5.8

Control Cables
Cables de Control
Cabos de Controle



Remote HMI
HMI Remoto
HMI Remota

* Torque { M3: 0.5 N.m (4.4 lbf.in)
M4: 1.7 N.m (15.0 lbf.in)

Document: 0899.5320 / 02

Language: English/ Español/Português